



Lot traceability, also called lot tracking, lot control or manufacturing traceability, means it is known which supplier lots were used in which finished products, and who received those finished products.

Lot control is the process of using procedures such as assigning lot IDs, and tracking parameters such as status and expiration date, for each lot (batch) as it moves through the system.

ASC requires both processes be employed for each item supplied to each customer.

Phone: 817-640-1300 • Fax 1-817-649-2685 • E-mail: ascind@ascintl.com